



GARY R. HERBERT
Governor
GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

April 13, 2012

Reviewed: 

Mine Name: Coyote Knoll 1-2-3 2	Permit Number: S/023/0086
Operator Name: Amnor Energy	Inspection Date: April 12, 2012
Inspector(s): Wayne Western	Time: 2:00- 2:20 pm
Other Participants: none	Mine Status: ACT
Weather Condition: 40's and rain	Last Inspection: March 24, 2012
Bond Renewal Date: October 26, 2015	Bond Amount: \$25,100.00
Surface Ownership: BLM	Mineral Ownership: Fee
Last Year of Production: 2005	Acreage: 5 acres

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Bond/Bond Release	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Annual Fees	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Annual Report	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The bond and permit fees are current.

The Permittee did not send in the annual report for 2011.

There are no shafts or adits at the site but there is a highwall associated with the pit. There are warning signs at the entrance.

There are no signs of erosion.

The fuel tanks were in a containment pit.

No one was at the site during the inspection.

Conclusions and Recommendations:

The Division should continue to monitor the site.

Directions to Site:

Inspector's Signature

A handwritten signature in blue ink, appearing to read "Wayne W. Hester", is written over a horizontal line.

WHW:

cc: (OPERATOR)

Jerry Mansfield BLM

O:\M023-Juab\S0230086-CoyoteKnoll\inspections\Insp041220121.doc



Entrance sign



Overview of storage/waste area



Facility area



Facility area fuel storage